ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0417, W0411, W0232, W0415	NA	Navodaya School Road
Segment No.	**Total Length (m)**	
11/C-W0417/S105958	221.39	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	221.39	77.540401	13.078799	77.542391	13.078381	W0391	W0419

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Culverts and Providing Covering Slab to Existing Drians and Kerb at Navodaya School Road in ward no 11 Kuvempunagara Vidyaranayapura S	2000000	2015
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of Culverts and Providing Covering Slab to Existing Drians and Kerb at Navodaya School Road in ward no 11 Kuvempunagara Vidyaranayapura Sub-Division Yelahanka zone	011-15-000062
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/ EE/BTP/WO/29/2016-17	05/05/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
05/05/2016	04/05/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
GOPI REDDY		0.00
Phone No.	**E-Mail ID**	
7760405418		

Field Inspection Details

Number of Trees	Any Other Information	Name
12		SURESH

Date of Inspection	Remarks
29/11/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0417, W0411, W0232, W0415

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	29/11/2016	29/12/2016	COMPLETED
SE	VASU K M	29/11/2016	29/12/2016	COMPLETED
EE	YARAPPA REDDY	29/11/2016	29/12/2016	COMPLETED
AEE	SHIVAKUMAR	29/11/2016	29/12/2016	COMPLETED
AE	SURESH	29/11/2016	29/12/2016	COMPLETED
AE	SURESH	29/11/2016	29/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0417, W0411, W0232, W0415